

Impact of Improper Identification of Certain Resin Products Manufactured by Toray Industries as received UL Certification on Figaro Products

On January 31, 2022, Toray Industries, Inc. announced that certain resin products were improperly identified by Toray as receiving certification from Underwriters Laboratories (hereinafter, "UL"). For more details, please refer to the following notice published on the website of Toray Industries, Inc.:

<https://www.toray.com/global/news/details/20220131151731.html>

We would like to report impact and countermeasures for our products in which the said Toray resin products are used:

1. Product models:

- TGS6810
- TGS6812
- CGM6812

(These sensors have not obtained UL certification as recognized components.)

2. Impact on Figaro products:

Figaro considers that the said materials possess sufficient flame retardancy in their molded part shapes for Figaro products, and that there is no problem in practical applications. Accordingly, we plan to continue supply of the above listed products as before. We are currently conducting confirmation and evaluation of alternative materials, and will continue to take measures where necessary.

Should you have any questions, please do not hesitate to contact us.